



For use with: W 61, W 101, W 201

| Description and Model | Width A | Order-No. 260°C | Order-No. 310°C | Order-No. 370°C | Order-No. 425°C |
|-----------------------|---------|--------------------|--------------------|--------------------|--------------------|
|-----------------------|---------|--------------------|--------------------|--------------------|--------------------|


For 60 W soldering iron (W61)

| | | | | | |
|--|--------|-----------------------------|-----------------------------|-------------------------------|-----------------------------|
| Chisel tip straight  | 1,6 mm | CT5A5 5 42 005 99 | CT5A6 5 42 006 99 | CT5A7 5 42 007 99 | CT5A8 5 42 008 99 |
| | 2,4 mm | CT5B5 5 42 015 99 | CT5B6 5 42 016 99 | CT5B7 ① 5 42 017 99 | CT5B8 5 42 018 99 |
| | 3,2 mm | CT5C5 5 42 025 99 | CT5C6 5 42 026 99 | CT5C7 5 42 027 99 | CT5C8 5 42 028 99 |
| | 5,0 mm | CT5D5 5 42 035 99 | CT5D6 5 42 036 99 | CT5D7 5 42 037 99 | CT5D8 5 42 038 99 |


| | | | | | |
|--|--------|------------------------------|------------------------------|------------------------------|------------------------------|
| Chisel tip bent (45°)  | 1,6 mm | CT5AX5 5 42 105 99 | CT5AX6 5 42 106 99 | CT5AX7 5 42 107 99 | CT5AX8 5 42 108 99 |
| | 2,4 mm | CT5BX5 5 42 115 99 | CT5BX6 5 42 116 99 | CT5BX7 5 42 117 99 | CT5BX8 5 42 118 99 |
| | 3,2 mm | CT5CX5 5 42 125 99 | CT5CX6 5 42 126 99 | CT5CX7 5 42 127 99 | CT5CX8 5 42 128 99 |
| | 5,0 mm | CT5DX5 5 42 135 99 | CT5DX6 5 42 136 99 | CT5DX7 5 42 137 99 | CT5DX8 5 42 138 99 |

For 100 W soldering iron (W101)

| | | | | | |
|--|--------|---|-----------------------------|-------------------------------|-----------------------------|
| Chisel tip straight  | 3,2 mm | - | CT6C6 5 42 206 99 | CT6C7 5 42 207 99 | CT6C8 5 42 208 99 |
| | 5,0 mm | - | CT6D6 5 42 216 99 | CT6D7 5 42 217 99 | CT6D8 5 42 218 99 |
| | 7,0 mm | - | CT6E6 5 42 226 99 | CT6E7 ① 5 42 227 99 | CT6E8 5 42 228 99 |

| | | | | | |
|--|--------|---|------------------------------|------------------------------|------------------------------|
| Chisel tip bent (45°)  | 3,2 mm | - | CT6CX6 5 42 306 99 | CT6CX7 5 42 307 99 | CT6CX8 5 42 308 99 |
| | 5,0 mm | - | CT6DX6 5 42 316 99 | CT6DX7 5 42 317 99 | CT6DX8 5 42 318 99 |
| | 7,0 mm | - | CT6EX6 5 42 326 99 | CT6EX7 5 42 327 99 | CT6EX8 5 42 328 99 |

For 200 W soldering iron (W201)

| | | | | | |
|--|---------|---|-----------------------------|-------------------------------|-----------------------------|
| Chisel tip straight  | 7,0 mm | - | CT2E6 5 42 406 99 | CT2E7 5 42 407 99 | CT2E8 5 42 408 99 |
| | 10,0 mm | - | CT2F6 5 42 416 99 | CT2F7 ① 5 42 417 99 | CT2F8 5 42 418 99 |
| | 11,0 mm | - | CT2G6 5 42 426 99 | CT2G7 5 42 427 99 | CT2G8 5 42 428 99 |

| | | | | | |
|--|---------|---|------------------------------|------------------------------|------------------------------|
| Chisel tip bent  | 7,0 mm | - | CT2EX6 5 42 506 99 | CT2EX7 5 42 507 99 | CT2EX8 5 42 508 99 |
| | 10,0 mm | - | CT2FX6 5 42 516 99 | CT2FX7 5 42 517 99 | CT2FX8 5 42 518 99 |

① Scope of delivery W61